

THERMOMETERS



DIAL BIMETAL POCKET THERMOMETER

Measuring range: - 10°C to + 100°C / 1°C
Measuring probe st. steel, 125mm and protective plastic sleeve.

Code

BOE 316



DIGITAL POCKET THERMOMETER

Measuring range: - 50°C to + 300°C / 0,1°C
Measuring probe st. steel, 120mm and protective plastic sleeve.
Min/Max memory, Measuring time 1 or 10 sec.
Selectable °C/°F, with battery (button cell, 1 pc.)

Code

BOE 310



DIGITAL WATERPROOF THERMOMETER

Pocket size, with easy to read Jumbo Display
Measuring range: - 50°C to + 300°C
Accuracy: $\pm 1^\circ\text{C}$ in the range of -30° till $+150^\circ$, otherwise $\pm 2^\circ\text{C}$
Visible 115 mm stainless steel piercing sensor probe
IP67 waterproof.
Alarm at high-/low temperature
Max/Min ($^\circ\text{C}$) Memory recalling. One hour auto shut off
With battery, (button cell, 1 pc.)

Code

BOE 311



DIGITAL WATERPROOF THERMOMETER

Measuring range: - 50°C to + 300°C
Resolution: $\pm 0,1^\circ\text{C}$ for $19,9^\circ$ till $+199,9^\circ$, otherwise 1°C
Accuracy $\pm 1^\circ\text{C}$ in the range of 151°C till $+ 250^\circ\text{C}$, otherwise $\pm 2^\circ\text{C}$.
130 mm stainless steel temperature sensor probe, with 1 metre wire,
alarm at high-/low temperature
Selectable $^\circ\text{C}/^\circ\text{F}$, Max/Min ($^\circ\text{F}/^\circ\text{C}$) memory recalling
without auto shutt off - **suitable for overnight Max/Min measurements**
IPX5 waterproof.
With battery (button cell, 1 pc.)

Code

BOE 305

MAX/MIN THERMOMETER

MAXIMA/MINIMA THERMOMETER

mercury free

Measuring range: -30°C to + 50°C


with push button for automatic resetting

Ivory coloured plastic housing with removable top shield and eyelet for wall mounting

Size: 230 x 55 mm

Code

BOE 23940



DIGITAL MAX/MIN THERMOMETER

Display with current temperature, minimum temperature and maximum temperature

Indoor/outdoor minimum and maximum temperature measurement

Temperature measuring range:

Indoor: -5°C to + 50°C (+23°F to +122°F)

Outdoor: -50°C to + 70°C (-58°F to +158°F)

With sensor probe for outdoor minimum and maximum temperature measurement

Supplied with wire holder for fixing sensor probe on wall

Table standing and hanging features

Size: 66 x 68 x 21 mm (L x W x H)

Battery: 1 x button cell

Code

BOE 325



DIGITAL JUMBO MAX/MIN THERMOMETER

°F/°C, Max/Min (°F/°C) memory

Instant reading of Max/Min temperature record or High/low alarm setting

Alerting alarm beeps and flashing symbol displays when temperature reaches/beyond the pre-set limit

Jumbo LCD Display with digit height 35 mm

Flip out stand and hanging hole at the back of the unit

Measuring range: -50°C to +70°C or -58°F to +158°F

Accuracy: 1°C or ±1,8°F in the range of 0°C to +50°C or 32°F to +122 °F

otherwise more than ±1°C or ±1,8°F

Resolution: 0,1° for the whole range

Ambient temp. for the plastic case:

0°C till +50°C or 32°F till +122°

External sensor: 3m sensor wire with probe (22,5 x ø 5,5 mm) for outdoor temperature measurement

Size: 120 x 110 x 25 mm,

Battery: 1 x AAA (1,5VDC) battery incl.

Code

BOE 328



THERMO-HYGROMETERS

DIGITAL MAX/MIN THERMO HYGROMETER



Current Indoor and Outdoor temperature,
and indoor humidity in the display
Indoor/Outdoor min. / max. measurement by pressing the MAX./MIN key

Measuring range:
IN: 0°C to + 50°C / 1°C (+32°F to 122°F)
OUT: - 50°C to + 70°C / 1°C (-58°F to +158°F)
Indoor hygro range: 20 to 98 RH / ± 5%
Supplied with 1,5 m cable sensor probe for outdoor min.
and max temp. measurement
Size: 123 x 70 x 20 mm,
Battery: 1 xAAA (1,5VDC) battery included

Code

BOE 326

DIGITAL THERMO- / HYGROMETER



Dual LCD display with indoor temp. and relative
indoor humidity at the same time.

Measuring range:
Indoor temp.: 0°C to + 50°C /1°C
Rel. humidity indoor: 25% to 95%/1%
with battery (AAA, 1pc.)

Code

BOE 330

DIGITAL THERMO-HYGROMETER & CLOCK



Display Indoor Temperature and Humidity, Outdoor temperature
record the maximum and minimum temperature and humidity
°C and °F switch
Freeze alert from -1°C to +4°C

Temperature measuring range:
Indoor: -10 to + 50°C (+14 to +122 °F)
Outdoor: -5 to + 70°C (-58 to + 158°F)

Humidity measuring range:
20 – 99 %RH

Accuracy:
± 1°C,
± 5% RH

1 x battery (AAA) incl.

Code

BOE 327